



Service Bulletin

File in Section: -

Bulletin No.: PIC6009

Date: June, 2014

PRELIMINARY INFORMATION

Subject: Rear Sway Bar Not Present On Vehicles Equipped With 4-Wheel Independent Suspension (RPO FE1)

Models: 2014 Chevrolet Corvette
Equipped with 4-Wheel Independent Suspension (RPO FE1)

Condition/Concern

A dealer or customer may inquire as to whether or not a rear sway bar can be added to a vehicle that was not originally equipped with one. The rear sway bar is part of the Z51 Performance Package.

Recommendation/Instructions

Important: GM does NOT recommend or support this modification.

Do NOT install a rear sway bar on a vehicle not originally equipped with the Z51 Performance Package. The FE1 suspension system was designed and tested without a rear sway bar. Installing a rear sway bar on a FE1 (non-Z51) vehicle may cause concerns with vehicle control, ride and handling.